

Table ENG-6. - Sanitary Facilities

Albemarle County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:							
Abell	80	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to bedrock	0.61
		Depth to bedrock	1.00	Depth to bedrock	0.61	Too clayey	0.50
		Too clayey	0.50			Depth to saturated zone	0.25
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
2B:							
Albemarle	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50				
2C:							
Albemarle	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Slope	0.37
2D:							
Albemarle	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
3C:							
Albemarle	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Slope	0.37
3D:							
Albemarle	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50
3E:							
Albemarle	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Too clayey	0.50

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
4B:							
Ashe	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
4C:							
Ashe	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
4D:							
Ashe	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
4E:							
Ashe	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
5B:							
Belvoir	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thin cemented pan	0.50	Depth to saturated zone	1.00	Depth to saturated zone	1.00
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
6:							
Bermudian	85	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.21
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Gravel content	0.14
		Seepage	1.00	Seepage	1.00		
Wehadkee	3	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
7B:							
Braddock	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
7C:							
Braddock	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
7D:							
Braddock	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
8C3:							
Braddock	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
9B:							
Braddock	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
9C:							
Braddock	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
9D:							
Braddock	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
10:							
Buncombe	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Too Sandy	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
		Too Sandy	1.00				
Frequently Flooded	3	Not Rated		Not Rated		Not Rated	
11D:							
Cataska	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
Hartleton	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Gravel content	0.91
		Seepage	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
11E:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
11E:							
Cataska	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
Hartleton	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Gravel content	0.91
		Seepage	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
12C:							
Catoclin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.58
		Slope	0.37	Slope	0.37	Seepage	0.50
12D:							
Catoclin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.58
12E:							
Catoclin	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.58
13C:							
Catoclin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Gravel content	0.49
13D:							
Catoclin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
13E:							
Catoclin	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
14B:							
Chester	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
14C:							
Chester	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
14D:							
Chester	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
14E:							
Chester	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
15C:							
Chester	75	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Slope	0.37
		Slope	0.37				
15D:							
Chester	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00	Slope	1.00
		Slope	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
15E:							
Chester	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00	Slope	1.00
		Slope	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
16:							
Chewacla	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
Wehadkee	3	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
17:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
17:							
Craigsville	70	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Seepage	1.00
		Seepage	1.00	Seepage	1.00	Content of large stones	0.84
		Content of large stones	0.84			Gravel content	<0.01
Poorly Drained	5	Not Rated		Not Rated		Not Rated	
18B:							
Creedmoor	80	Very limited		Somewhat limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	0.92	Too clayey	1.00
		Too clayey	1.00			Depth to saturated zone	0.95
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
19B:							
Cullen	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
19C:							
Cullen	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
19D:							
Cullen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
20B3:							
Cullen	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
20C3:							
Cullen	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
20D3:							
Cullen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50

21B:

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
21B:							
Culpeper	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.84	Depth to bedrock	0.84
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
21C:							
Culpeper	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.84	Depth to bedrock	0.84
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
21D:							
Culpeper	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.84	Depth to bedrock	0.84
		Too clayey	0.50			Too clayey	0.50
22C3:							
Culpeper	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.84	Depth to bedrock	0.84
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
23B:							
Davidson	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
23C:							
Davidson	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
24B:							
Dogue	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to saturated zone	0.68
		Seepage	1.00				
25B:							
Dyke	85	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
25C:							
Dyke	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37

26B3:

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
26B3: Dyke	85	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
26C3: Dyke	85	Very limited Too clayey Slope	1.00 0.37	Somewhat limited Slope	0.37	Very limited Too clayey Slope	1.00 0.37
26D3: Dyke	85	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
27B: Elioak	80	Not limited		Not limited		Somewhat limited Too clayey Hard to compact	0.50 0.50
27C: Elioak	80	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Hard to compact Slope	0.50 0.50 0.37
27D: Elioak	80	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope Too clayey Hard to compact	1.00 0.50 0.50
28C3: Elioak	80	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Hard to compact Slope	0.50 0.50 0.37
28D3: Elioak	80	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope Too clayey Hard to compact	1.00 0.50 0.50
29B: Fauquier	85	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
29C:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
29C:							
Fauquier	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	1.00
		Slope	0.37			Slope	0.37
29D:							
Fauquier	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	1.00
29E:							
Fauquier	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	1.00
30C3:							
Fauquier	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	1.00
		Slope	0.37			Slope	0.37
30D3:							
Fauquier	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	1.00
31C:							
Fauquier	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	1.00
		Slope	0.37			Slope	0.37
31D:							
Fauquier	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	1.00
32B:							
Fluvanna	80	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
32C:							
Fluvanna	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
33C:							
Fluvanna	80	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
34B:							
Glenelg	90	Not limited		Not limited		Not limited	
34C:							
Glenelg	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Slope	0.37
34D:							
Glenelg	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
34E:							
Glenelg	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
35C:							
Hartleton	60	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Gravel content	0.91
		Seepage	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Slope	0.37	Slope	0.37	Slope	0.37
Cataska	30	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
		Slope	0.37	Slope	0.37	Seepage	1.00
36B:							
Hayesville	80	Very limited		Not limited		Somewhat limited	
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
36C:							
Hayesville	80	Very limited		Somewhat limited		Somewhat limited	
		Seepage	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
		Slope	0.37			Slope	0.37
36D:							
Hayesville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
36E:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
36E:							
Hayesville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
37B3:							
Hayesville	80	Very limited		Not limited		Somewhat limited	
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
37C3:							
Hayesville	80	Very limited		Somewhat limited		Somewhat limited	
		Seepage	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
		Slope	0.37			Slope	0.37
37D3:							
Hayesville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
37E3:							
Hayesville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
38C:							
Hayesville	75	Very limited		Somewhat limited		Somewhat limited	
		Seepage	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
		Slope	0.37			Slope	0.37
38D:							
Hayesville	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
38E:							
Hayesville	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50			Hard to compact	0.50
39C:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
39C:							
Hazel	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Slope	0.37
39D:							
Hazel	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
39E:							
Hazel	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
40D:							
Hazel	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
40E:							
Hazel	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
41B:							
Hiwassee	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
41C:							
Hiwassee	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
42B3:							
Hiwassee	85	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
42C3:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
42C3:							
Hiwassee	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
42D3:							
Hiwassee	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
43B:							
Klinesville	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00			Gravel content	0.93
						Seepage	0.50
43C:							
Klinesville	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Slope	0.37	Gravel content	0.93
		Slope	0.37			Seepage	0.50
43D:							
Klinesville	90	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	0.93
43E:							
Klinesville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	0.93
44C:							
Lew	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Gravel content	0.63
		Slope	0.37			Too clayey	0.50
		Content of large stones	0.01			Slope	0.37
44D:							
Lew	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Gravel content	0.63
		Content of large stones	0.01			Too clayey	0.50
45C:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
45C:							
Lew	85	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Gravel content	0.63
		Slope	0.37			Too clayey	0.50
		Content of large stones	0.01			Slope	0.37
45D:							
Lew	90	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Gravel content	0.63
		Content of large stones	0.01			Too clayey	0.50
46B:							
Lignum	85	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.96
		Depth to bedrock	1.00	Depth to bedrock	0.01	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.01
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
47C:							
Louisburg	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00	Slope	0.37	Slope	0.37
		Slope	0.37				
47D:							
Louisburg	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00				
47E:							
Louisburg	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00				
48D:							
Louisburg	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00				
48E:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
48E:							
Louisburg	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00				
49B:							
Manassas	80	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Too clayey	0.50
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.47
		Seepage	1.00	Seepage	1.00	Seepage	0.21
50D:							
Manor	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
50E:							
Manor	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.21
51B:							
Manteo	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.89
						Seepage	0.50
51C:							
Manteo	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.89
		Slope	0.37	Slope	0.37	Seepage	0.50
51D:							
Manteo	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.89
51E:							
Manteo	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.89
52D:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
52D:							
Manteo	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.99
52E:							
Manteo	90	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.99
53B:							
Masada	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
53C:							
Masada	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
54B:							
Mayodan	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.18	Too clayey	0.50
		Too clayey	0.50			Depth to bedrock	0.18
54C:							
Mayodan	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50	Depth to bedrock	0.18	Slope	0.37
		Slope	0.37			Depth to bedrock	0.18
55B:							
Mcqueen	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00	Flooding	0.40		
		Flooding	0.40				
56B:							
Meadowville	75	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Seepage	0.21
		Seepage	1.00	Seepage	1.00		
56C:							
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
56C:							
Meadowville	80	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Slope	0.37
		Seepage	1.00	Seepage	1.00	Seepage	0.21
		Slope	0.37	Slope	0.37		
57B:							
Mount Lucas	80	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.96
		Depth to bedrock	1.00			Too clayey	0.50
		Seepage	1.00				
Worsham	3	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
58B:							
Myersville	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
58C:							
Myersville	80	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
58D:							
Myersville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
58E:							
Myersville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
59C:							
Myersville	85	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37

59D:

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
59D:							
Myersville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
59E:							
Myersville	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
60C:							
Myersville	70	Very limited		Somewhat limited		Somewhat limited	
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
Catoctin	25	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Gravel content	0.49
60D:							
Myersville	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
Catoctin	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
60E:							
Myersville	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50
Catoctin	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
61D:							
Myersville	60	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.88	Depth to bedrock	0.88
		Too clayey	0.50			Too clayey	0.50

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
61D: Rock Outcrop	25	Not Rated		Not Rated		Not Rated	
61E: Myersville	60	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 0.88	Very limited Slope Depth to bedrock Too clayey	1.00 0.88 0.50
Rock Outcrop	25	Not Rated		Not Rated		Not Rated	
62B: Nason	80	Very limited Depth to bedrock Too clayey	1.00 0.50	Somewhat limited Depth to bedrock	0.42	Somewhat limited Too clayey Depth to bedrock	0.50 0.42
62C: Nason	80	Very limited Depth to bedrock Too clayey Slope	1.00 0.50 0.37	Somewhat limited Depth to bedrock Slope	0.42 0.37	Somewhat limited Too clayey Depth to bedrock Slope	0.50 0.42 0.37
62D: Nason	80	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Slope Depth to bedrock	1.00 0.42	Very limited Slope Too clayey Depth to bedrock	1.00 0.50 0.42
63B: Orange	80	Very limited Depth to saturated zone Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to bedrock	1.00 0.08	Very limited Too clayey Depth to saturated zone Depth to bedrock	1.00 1.00 0.08
64B: Orange	80	Very limited Depth to saturated zone Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to bedrock	1.00 0.08	Very limited Too clayey Depth to saturated zone Depth to bedrock	1.00 1.00 0.08
65B: Pacolet	80	Not limited		Not limited		Somewhat limited Hard to compact	0.50
65C: Pacolet	80	Somewhat limited Slope	0.37	Somewhat limited Slope	0.37	Somewhat limited Hard to compact Slope	0.50 0.37

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
66C:							
Parker	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00	Slope	0.37	Content of large stones	1.00
		Content of large stones	1.00			Slope	0.37
66D:							
Parker	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00			Content of large stones	1.00
66E:							
Parker	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00			Content of large stones	1.00
67D:							
Parker	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00			Content of large stones	1.00
67E:							
Parker	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	1.00
		Seepage	1.00			Content of large stones	1.00
68B:							
Penn	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
		Too clayey	0.50			Too clayey	0.50
68C:							
Penn	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
68D:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
68D:							
Penn	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.67
69:							
Pits	85	Not Rated		Not Rated		Not Rated	
Water	3	Not Rated		Not Rated		Not Rated	
70C:							
Porters	80	Very limited		Very limited		Somewhat limited	
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
		Seepage	1.00	Slope	0.37	Slope	0.37
		Slope	0.37				
70D:							
Porters	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
		Seepage	1.00				
70E:							
Porters	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Seepage	0.50
		Seepage	1.00				
71B:							
Rabun	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
71C:							
Rabun	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
71D:							
Rabun	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
71E:							
Rabun	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	0.50			Too clayey	0.50
72B3:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
72B3: Rabun	80	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
72C3: Rabun	80	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
72D3: Rabun	80	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
72E3: Rabun	80	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
73C: Rabun	85	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
73D: Rabun	80	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
73E: Rabun	75	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
74B: Rapidan	85	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
74C: Rapidan	85	Very limited Too clayey Slope	1.00 0.37	Somewhat limited Slope	0.37	Very limited Too clayey Slope	1.00 0.37
74D: Rapidan	75	Very limited Slope Too clayey	1.00 1.00	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 1.00
75C3:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
75C3:							
Rapidan	85	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
75D3:							
Rapidan	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
76:							
Riverview	75	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.50
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
		Seepage	1.00	Seepage	1.00		
Wehadkee	3	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
77:							
Riverview	50	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.50
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
		Seepage	1.00	Seepage	1.00		
Chewacla	40	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
Wehadkee	3	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
78:							
Rowland	85	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	0.86
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
78: Wehadkee	3	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
79B: Starr	80	Very limited Flooding Too clayey	1.00 0.50	Very limited Flooding	1.00	Somewhat limited Too clayey	0.50
80B: Tatum	80	Very limited Depth to bedrock Too clayey	1.00 1.00	Somewhat limited Depth to bedrock	0.32	Very limited Too clayey Depth to bedrock	1.00 0.32
80C: Tatum	80	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.37	Somewhat limited Depth to bedrock Slope	0.42 0.37	Very limited Too clayey Depth to bedrock Slope	1.00 0.42 0.37
81B: Thurmont	80	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
81C: Thurmont	80	Very limited Depth to saturated zone Too clayey Slope	1.00 0.50 0.37	Very limited Depth to saturated zone Slope	1.00 0.37	Somewhat limited Too clayey Slope	0.50 0.37
81D: Thurmont	75	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
82C: Thurmont	75	Very limited Depth to saturated zone Too clayey Slope	1.00 0.50 0.37	Very limited Depth to saturated zone Slope	1.00 0.37	Somewhat limited Too clayey Slope	0.50 0.37

82D:

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
82D:							
Thurmont	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Slope	1.00	Slope	1.00
		Slope	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
83:							
Toccoa	85	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.50
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
		Seepage	1.00	Seepage	1.00		
Wet Spots	3	Not Rated		Not Rated		Not Rated	
84B:							
Totier	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.54	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.54
84C:							
Totier	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.54	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	0.54
		Slope	0.37			Slope	0.37
85C3:							
Totier	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.54	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	0.54
		Slope	0.37			Slope	0.37
86B:							
Turbeville	80	Somewhat limited		Not limited		Somewhat limited	
		Too clayey	0.50			Too clayey	0.50
						Hard to compact	0.50
86C:							
Turbeville	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Hard to compact	0.50
						Slope	0.37
87B:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
87C:							
Tusquitee	85	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
87D:							
Tusquitee	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Too clayey	0.50			Too clayey	0.50
88:							
Udorthents	85	Not Rated		Not Rated		Not Rated	
Wet Spots	3	Not Rated		Not Rated		Not Rated	
89B:							
Unison	80	Very limited		Not limited		Somewhat limited	
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50				
89C:							
Unison	80	Very limited		Somewhat limited		Somewhat limited	
		Seepage	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Slope	0.37
		Slope	0.37				
90B:							
Unison	80	Very limited		Not limited		Somewhat limited	
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50				
90C:							
Unison	75	Very limited		Somewhat limited		Somewhat limited	
		Seepage	1.00	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Slope	0.37
		Slope	0.37				
90D:							
Unison	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00			Too clayey	0.50
		Too clayey	0.50				
91:							
Urban Land	85	Not Rated		Not Rated		Not Rated	
92:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
92:							
Wahee	80	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
Wehadkee	3	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
93C:							
Watt	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Slope	0.37	Slope	0.37	Gravel content	0.49
93D:							
Watt	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
93E:							
Watt	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	0.50
94B:							
Wedowee	80	Not limited		Not limited		Somewhat limited	
						Hard to compact	0.50
94C:							
Wedowee	80	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.37	Slope	0.37	Hard to compact	0.50
						Slope	0.37
95:							
Wehadkee	80	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50				
96B:							

Table ENG-6. - Sanitary Facilities - Continued

Albemarle County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
96B:							
Worsham	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
W:							
Water	100	Not Rated		Not Rated		Not Rated	